

In-class assignment and Homework (due 10/13*)

- 1. Please read all three SparkFun tutorials listed near the start of unit 3 writeup.
- 2. SPI and I2C BME: Wire up and demonstrate 2 BME sensors, one with I2C interface (original), the other with SPI

* With all troubleshooting, if needed; as a practical matter it should be running by 10/8